



COTTON (SULZER QUALITY LIST)

S.NO	QUALITY	WIDTH	HSN CODE	G.L.M	G.S.M	YARN TYPE	WEAVE
1	07X07/68X38	63	520912	625	391	OE X OE	DRILL
2	10X06/76X28	63	520912	520	322	OE X OE	DUCK
3	10X10/40X36	63	520812	310	194	OE X OE	PLAIN
4	10X10/68X38	63	520912	450	272	OE X OE	DRILL
5	16X08/84X28	48	520912	275	226	OE X OE	DUCK
6	16X08/84X28	63	520912	365	226	OE X OE	DUCK
7	16X10/84X28	63	520912	340	210	OE X OE	DUCK
8	16X12/84X28	48	520812	235	194	OE X OE	DUCK
9	16X12/84X26	63	520812	310	194	OE X OE	DUCK
10	16X12/96X48	63	520912	415	259	OE X OE	DRILL
11	16X12/108X56	63	520912	470	294	OE X OE	DRILL
12	16X16/60X56	63	520812	295	184	OE X OE	PLAIN
13	16X16/60X56	72	520812	340	184	OE X OE	PLAIN
14	2/20X10/40X36	48	520812	236	194	OE X OE	PLAIN
15	2/20X10/40X36	63	520812	310	194	OE X OE	PLAIN
16	2/20X10/40X36	67	520812	330	194	OE X OE	PLAIN
17	20X16/108X56	63	520912	355	222	OE X OE	DRILL
18	20X20/52X48	63	520812	205	128	OE X OE	PLAIN
19	20X20/52X48	67	520812	218	128	OE X OE	PLAIN
20	20X20/60X50	63	520812	225	141	OE X OE	PLAIN
21	20X20/60X56	120	520812	455	149	OE X OE	PLAIN
22	20X20/60X60	50	520812	194	153	OE X OE	PLAIN
23	20X20/60X56	63	520812	240	151	OE X OE	PLAIN
24	20X20/60X60	63	520812	245	153	OE X OE	PLAIN
25	20X20/60X60	67	520812	260	153	OE X OE	PLAIN
26	20X20/60X60	72	520812	280	153	OE X OE	PLAIN
27	20X20/60X60	78	520812	304	153	OE X OE	PLAIN
28	20X20/96X48	63	520812	300	190	OE X OE	DRILL
29	20X20/108X56	63	520912	330	206	OE X OE	DRILL
30	20X20/108X56	67	520912	350	206	OE X OE	DRILL
31	20X20/108X56	72	520912	377	206	OE X OE	DRILL
32	30X30/68X64	63	520812	175	109	RS X OE	PLAIN
33	30X30/76X68	65	520812	195	118	CARDED	PLAIN
WARP - OE X WEFT - SPANDEX YARN 70 DENIER							
34	20X16/108X56	63	520912	350	222	OE X RS	DRILL